HO-983

3505 Route 32 West Friendship vicinity public

Description:

The house is a 1 ½-story, three-bay by two bay rubble stone veneer structure with a gable roof that has asphalt shingles and a north-south ridge. There is a one-story garage wing on the north end that is one bay by one bay, and has matching walls and roof. The west elevation has a center door in the main block and three gable-roofed dormers. The west elevation of the garage, which is set back from the west plane of the main block, has T1-11 infill in the large doorway. The roof is cantilevered out on the west. The south elevation has a one-story, hipped roof porch on stone piers, with a flagstone deck. The east elevation has a large shed-roofed dormer.

Significance:

The house at 3505 Route 32 is a standard Cape Cod that was reportedly built in 1948, according to the Maryland Department of Assessments and Taxation, and there is no reason to believe this date is appreciably wrong. It is a form popularized beginning in the 1930s, but especially in the 1940s and 1950s with the post-war suburbanization of the United States; it was found throughout rural areas, as well, since national trends had sublimated traditional building practices by this time. It fit within the popular Colonial Revival mode and the compact form made it affordable for many. This example is unusual in having stone veneer on all four sides, which must have pushed it to the high end of the middle class economic scale. It was demolished in 2009 as part of the alterations to Route 32.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

1. Name of I	Property	(indicate preferred na	ame)		
historic					
other					<u> </u>
2. Location					
street and number	3505 Route 32			s 3	not for publication
city, town	West Friendship	o		<u>X</u>	vicinity
county	Howard				
3. Owner of	Property	(give names and mailing	addresses of all ow	ners)	
name	State Highway	Administration			-
street and number	301 W. Preston	Street		telephone	
city, town	Baltimore		state MD	zip code 2	21201-2305
4. Location courthouse, registr		Howard County Courthouse	li	ber 10742 folio 19	6
courthouse, registr	y of deeds, etc. I Ellicott City	tax map 22	tax parcel 37		
Contr Deter Deter Recor	buting Resource in mined Eligible for mined Ineligible for ded by HABS/HAI	rt or Research Report at MHT	and Register		
6. Classifica	ition				45
Categorydistrict _Xbuilding(s)structuresiteobject	Ownership X public private both	Current Function agriculturecommerce/tradedefensedomesticeducationfunerary _X_governmenthealth careindustry	landscape recreation/cult religion social transportation work in progre unknown vacant/not in u	0 0 0 1 use Number of C	Noncontributing

	7.	Desc	ription
--	----	------	---------

Inventory No. HO-983

Condition

	_excellent	deteriorated
X	_ good	ruins
_	fair	altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

The house at 3505 Route 32 is located on the east side of the road, about mid-way between Ivory and Glenelg, in central Howard County, Maryland. It is a 1 ½-story, three-bay by two bay rubble stone veneer structure with a gable roof that has asphalt shingles and a north-south ridge. There is a one-story garage wing on the north end that is one bay by one bay, and has matching walls and roof. The west elevation has a center door in the main block that has a new six-panel door and plain pilasters and a pediment. On either side of the doorway is an eight-over-eight double hung sash. There is a wood box cornice and three gable-roofed dormers with vinyl siding and six-over-six sash. The south elevation has an exterior fireplace and chimney in the center, with a door in the west bay that has 15 lights and a six-over-six sash in the east bay. There is a one-story, hipped roof porch on stone piers, with a flagstone deck. The gable end has a small six-over-six sash on either side of the chimney.

The east elevation has a door in the center that has four lights over three lying panels. There are no openings to the south, but two windows to the north. They both have six-over-six sash, but the northern one is full size. There is a large shed-roofed dormer that has two small six-over-six sash, one in the center and one above the smaller sash on the first story. The garage wing is in the same plane as the back of the house and has a flush door on the first story and a dormer that matches those on the west. The north elevation of the garage has a six-over-six sash centered on the first story and a smaller six-over-six sash in the gable end. The west elevation of the garage, which is set back from the west plane of the main block, has T1-11 infill in the large doorway. The roof is cantilevered out on the west to cover a doorway on the north elevation of the main block, set to the west. This door has four lights over three lying panels.

The interior was not accessible during the site visit. There are no other buildings on the site. The house was demolished in 2009 as part of the alterations to Route 32.

8. Signification	ance			Inventory No. HO-983
Period	Areas of Significance	Check and ju	ustify below	
1600-1699 1700-1799 1800-1899 X 1900-1999 2000-	agriculture archeology X architecture art commerce communications community planning conservation	economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement	 health/medicine industry invention landscape architecture law literature maritime history military 	performing arts philosophy politics/government religion science social history transportation other:
Specific dates	N/A		Architect/Builder N/A	
Construction da	ates c. 1948			
Evaluation for:				
	National Register	N	laryland Register	Xnot evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

The house at 3505 Route 32 is a standard Cape Cod that was reportedly built in 1948, according to the Maryland Department of Assessments and Taxation, and there is no reason to believe this date is appreciably wrong. It is a form popularized beginning in the 1930s, but especially in the 1940s and 1950s with the post-war suburbanization of the United States; it was found throughout rural areas, as well, since national trends had sublimated traditional building practices by this time. It fit within the popular Colonial Revival mode and the compact form made it affordable for many. This example is unusual in having stone veneer on all four sides, which must have pushed it to the high end of the middle class economic scale. It was demolished in 2009 as part of the alterations to Route 32.

9. Major Bibliographical References

Inventory No. HO-983

10. Geographical Data

Acreage of surveyed property _	2.36 A		
Acreage of historical setting _	2.36 A		
Quadrangle name	Sykesville	Quadrangle scale:	1:24000

Verbal boundary description and justification

The boundaries consist of the property lines for tax map 22, parcel 37, which includes all of the historic resources on the site.

11. Form Prepared by


name/title	Ken Short			
organization	Howard County Department of Planning & Zoning	date	September 2009	
street & number	3430 Courthouse Drive	telephone	410-313-4335	
city or town	Ellicott City	state	Maryland	

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032-2023 410-514-7600



HO-983

3505 Route 32 Sykesville Quad

3505 Route 32 Howard County, Maryland Ken Short, photographer

Photo Log

Nikon D-70 camera HP Premium Plus paper HP Gray Photo print cartridge

HO-0983_2009-01-23_01 North & west elevations

HO-0983_2009-01-23_02 South & east elevations

HO-0983_2009-01-23 _03 East elevation



HO-983 3505 Route 32 Howard County, MD Ken Short Jan. 23, 2009 MDSHPO North & West Elevations





HO-983 3505 Rt. 32 Howard County, MO KenShort Jan. 23, 2009 MO SHPO South & East Elevations





HO-983 3505 Rt. 32 Howard County, MD Ken Short Jan. 23, 2009 MD SHPO · East Elevation

